Parts Change Information

Subject: New TR Side Frames for the Print Cylinder **ISSUE NO.: 091**

New Part# **New Description:** **Old Part#** **Old Description:**	**Reason For Change** **[ ] Cost Effective** **[ ] Eliminate Claims** **[ ] Easier Operation** **[X] Other**	**Manufacturing Cut in Serial#: See chart**	**Applies to:** **TR 1510**
[X] New	**[ ] Modified**	**[ ] Obsoleted**	**[ ] Other**

Summary:

New Squeegee Side Frames have the ball bearings pressure inserted.
The Squeegee (Doctor) Gap should be adjusted to 0.08 ± 0.02mm.



020-12515-408 Side Frame F; Squeegee

020-12518-300 Side Frame R; Squeegee

Serial Number Cut-in:

TR1510 - 80505402

Newly Registered Part: (Note: Parts may not be available for 120 days from date below)

020-12515-408	Side Frame F; Squeegee
020-12518-300	Side Frame R; Squeegee